

Joint Test Process at the Interconnection Distribution Frame (ICDF)

Description

Joint Testing Process at the ICDF allows a CLEC to request Qwest to joint test their terminations at the ICDF once their equipment has been placed in their Collocation.

Terms and Conditions

Qwest will only test between the Collocation and the ICDF.

CLEC will be allowed to request Joint Test from time of CLEC Application installation for up to 60 days past Ready for Service date.

Qwest will perform Joint Testing Process from the time of CLEC installation for up to 60 days past Ready for Service date.

CLEC must specify the type of test they want Qwest to perform with CLEC.

CLEC must provide contact information to Qwest.

The CLEC will be required to provide the installation administration (e.g. Method of Procedures and Completion Notifications) MOP in a manner that is consistent with other policies for all Qwest Collocation product offerings. Refer to Qwest's Technical Publication 77350 (<http://qwest.com/techpub/77350/77350.pdf>) for procedures.

CLEC will provide all test gear and enough technicians to operate the test gear. Qwest employees will not be able to operate CLEC test gear, but can be available to perform passive duties (e.g. read indications on a test set w/o adjusting the set)

Qwest will provide tools and materials for the repair of Qwest-network faults. If repair is needed it is performed at no charge to the CLEC.

Rate Elements

Non-Recurring Charges

This is a standard four hour charge plus any additional time on a per hour basis for time spent over the four hours for joint testing of the CLEC terminations at the ICDF. Please see Exhibit A of the SGAT (<http://qwest.com/about/policy/sgats>) for the relevant state.

Ordering

The Joint Test Process requires the submission of either a "Collocation New, Change and Augment Application form" with Joint Testing Process checked as part of a Collocation Application or utilize the separate Joint Testing Process application.

2.2.4For CO-Based Collocation, the "Collocation New, Change and Augment" and Joint Test Process Application form is located in the Ordering section of the Collocation – General Information web page at: <http://qwest.com/wholesale/pcat/collocation.html#apform>.

2.2.4The Joint Test Process Application should be submitted to both the Collocation Project Management Center (CPMC) at rfsmet@qwest.com and your Qwest Wholesale Collocation Project Manager at colo@qwest.com.

2.2.4

~~2.2.4~~ Once your application as has been validated Qwest will notify you and contact the identified person to set up the joint testing time once you have installed your equipment at your collocation.

~~2.2.4~~

~~2.2.4~~ Please review the test access points documents that is available at the following web page <http://qwest.com/wholesale/pcat/collocation>. This document will depict all of the allowable test access points based on the type of collocation requested.

~~2.2.4~~

~~2.2.4~~

~~2.2.4~~

~~2.2.4~~ Billing

~~2.2.4~~

~~2.2.4~~ You will receive a bill of a four hour minimum time for testing and any additional time on a per hour basis over the minimum. This will be from the BART billing system.